



International 49er/ 49erFX Class

EUROPEAN CHAMPIONSHIPS 2018

Approved Equipment Repair/Replacement Requests

Date	Class	Sail	Repair/Replacement	Equipment	Reason
		Number			
07/07/2018	49er	EST 321	Replacement	Jib	Signed in wrong sail, changed within Equipment Inspection time limit
07/07/2018	49er	POL 52	Replacement	Mainsail	Torn bolt rope on luff. Replacement sail number POL 997
07/07/2018	49er	POL 107	Replacement	Jib	Broken battens
08/07/2018	49erFX	ESP 212	Repair/Replacement	Spinnaker	Approved on-water replacement. Original spinnaker repaired.
08/07/2018	49er	CHN 253	Replacement	Mast	Broken spreaders
08/07/2018	49er	DEN 132	Replacement	Spinnaker	Torn

Rob Taylor 49er Class International Measurer